


7-552

1001

NOTES

1. DO NOT SCALE.
2. ALL OPERATES TO HAVE AEROSOLS AWARENESS TRAINING.
3. ROUTES TO BE REACHED AGAINST EXISTING SERVICE DRUMMINS TO ENSURE ALL KNOWN SERVICES ARE IDENTIFIED.
4. CAT SPANS TO BE CARRIED OUT ALONG PROPOSED ROUTES PRIOR TO EXCAVATION.
5. AREAS IDENTIFIED ON SERVICE DRUMMINS AND CAT SPANS AS HAVING THE POTENTIAL OF EXISTING SERVICES TO BE HAD DUG ONLY.
6. ENSURE A BANSUMAN IS IN PLACE AT ALL TIMES WHEN EXCAVATING USING MECHANICAL DIGGERS.
7. ALL DUGGING TO BE CARRIED OUT WITH CAUTION IN REGARDS TO BROWN FIELD SITES. SHOULD A CONCERN BE RAISED DURING EXCAVATION, WORKERS IN REGARDS TO THE TYPE OF SOIL, CONTAMINANTS OR COMPONENTS, WORKERS ARE TO STOP WORK IMMEDIATELY AND REPORT TO THE SITE SUPERVISOR. A REASON HAS BEEN PLACED AND A REGISTERED REPRESENTATIVE HAS CONTRIBUED THE AREA IS SAFE.
8. PLEASE REFER TO DRAWING 519865-INT-01 FOR DETAILS OF THE CABLE PITS AND TRENCHES.
9. PLEASE REFER TO DRAWING 519865-INT-01 FOR DETAILS AT BUILDING ENTRY POINTS.

Rev	Description	Date	Eng
Client			



Brunel University

PHASE 2
WORK PACK 06 – Civil Works
Maria Jahoda/Meeting House

NETWORK

status

Drawn	Checked	Size
SS	NC	A1
Job No	Scale	Date
519685	1:200	17/07/17

Drawing No	Rev
519685-P2-WP06	A